

IMPORTANT SAFETY RECALL

December 2014

This notice applies to your vehicle, VIN:	

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2007-2011 model year Chevrolet Silverado and GMC Sierra 2500/3500 series vehicles equipped with an auxiliary battery. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- Your vehicle is involved in safety recall 14260.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

General Motors recently discovered a data system issue which may have caused some current owners of vehicles -- that were originally purchased by fleet buyers in the U.S. and Canada -- to not receive certain recall communications from GM. This issue may have prevented prior letters concerning this recall from reaching you, which is why you are receiving this letter. We have corrected our data system and apologize for any delay in providing this letter to you.

In cooperation with the National Highway Traffic Safety Administration (NHTSA) we recommend that you check your vehicle identification number periodically at the GM recall website (https://recalls.gm.com) or at NHTSA's website (https://vinrcl.safercar.gov/vin/), where you can find the most up-to-date recall information for your vehicle.

Why is your vehicle being recalled?

The owner manual for vehicles with an auxiliary battery does not specify a maximum amperage rating for the auxiliary battery feed to a trailer harness. The auxiliary battery feed is equipped with a fusible link, designed to melt and open-circuit if an electrical overload occurs, in order to prevent damage or a possible fire in the vehicle wiring harness. However, if the fusible link melts in the event of an electrical overload, it may contact adjacent components and damage the electrical center cover, the nearby wiring harness conduit and other vehicle components, causing smoke or flames.

What will we do?

Your GM dealer will install a jumper harness with a 40A inline fuse. In addition, your dealer will provide you with a copy of an Owner Manual supplement. The supplement includes the maximum amperage rating for the auxiliary battery trailer feed with the 40 ampere inline fuse installed. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 25 minutes.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

Did you already pay for this repair?

Even though you may have already had repairs completed for this condition, you will still need to take your vehicle to your dealer for additional repairs. If you have paid for repairs for the recall condition and have not already submitted for reimbursement, please complete the enclosed reimbursement form and present it to your dealer with all required documents. Working with your dealer will expedite your request, however, if this is not convenient, you may mail the completed reimbursement form and all required documents to Reimbursement Department, PO Box 33170, Detroit, MI 48232-5170. The completed form and required documents must be presented to your dealer or received by the Reimbursement Department by September 30, 2015, unless state law specifies a longer reimbursement period.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)		
Chevrolet	1-800-222-1020	1-800-833-2438		
GMC	1-800-462-8782	1-888-889-2438		
Guam	65-6267-1752			
Puerto Rico – English	1-800-496-9992			
Puerto Rico – Español	1-800-496-9993			
Virgin Islands	1-800-496-9994			

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 14V407.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jeffrey M. Boyer Vice President Global Vehicle Safety

Enclosure GM Recall #14260

General Motors Product Field Action Customer Reimbursement Request Form

	This section to be	This section to be completed by customer (please print)						
Customer Name:								
Street Address or P. O	. Box Number:							
City:		State:	Zip Code:					
Daytime Telephone Nu	ımber (include Area C	Code):						
Evening Telephone Nu	ımber (include Area C	Code):						
Date Request Form an	d Supporting Docume	entation Submi	tted to Dealer:					
Vehicle Identification N	lumber of Involved Ve	ehicle:	(17 Char	acters)				
Mileage at Time of Rep	oair:	[ate of Repair:					
Amount of Reimbursen	nent Requested: \$							
THE FO	LLOWING DOCUMENTA	TION MUST ACC	OMPANY THIS REQ	UEST FORM.				
Original or clear copy of	of all receipts, invoices	s and/or repair	orders that show:					
 The Vehicle Ide Description of p The total cost of payme (Copy of cancelle) My signature to this do		(IN) of the vehing received at the control of the vehicles of	cle that was repain of repair and who quested. date of payment. ceipt for cash payment.	performed the repair. ent) ne and I request				
reimbursement for the Customer's Signature:	•	•	•					
and customary costs to considered for reimbur If your request is denie request is incomplete, request and offer you t	correct the condition sement. If your requence, you will receive a vocal your dealer will advise the opportunity to resuant questions about t	described in the st is approved written explanate you what door what the requestions or the state of the stat	ne letter that came, you will receive a tion for the denial aumentation is need st when the missipave waited 30 or	a check from your dealer. from your dealer. If your eded to complete the ing documents are r more days for a response				
This section to be completed by dealer (please print)								
Bulletin No.:	Request Approv	red: Date	:	Amount: \$				
Request Denied:	Date:	_ Reviewed B	/:					
Reason:								

If denied, please provide a copy of this form to the customer and retain original for your files